

**APPENDIX - VIII**


**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION  
CERTIFICATE.**

No. 05

Date : 18/07/26

It is certified that an inspection team headed by J.E Panchdewari  
Kunj Bihari (Name of Officers  
with designation) from Junior Engineer P.H.E.D (Name of  
Department/Office) inspected the Disha public School  
Panchdewari, Majharoliya, Nabardola, W.No-13 (Name & Address of  
the School) on 16/07/26 and found that the Disha public School (Name of school) has safe  
drinking water facilities for the students and members of staff of the institution and is maintaining  
the hygienic sanitation condition in the school building & the campus as per the norms  
prescribed by the Central/State/U.T Govt.

The above valid for a period of 6th month.

Signature with Seal : 

Name :

Md. Gauron Gh.

Designation :

Assistant Engineer.

**सहायक अभियंता**


**लोक स्वास्थ्य और प्रमोशन**

**जोपालनगर**

To

Disha public School  
Panchdewari, Majharoliya,  
Nabardola, W.No-13

(Name & Address of the Institution)

  
18/07/26  
Lab Asst